

LR0-D2 PA-1701



North

Site
entrance

END Mountain Road

slag pile
AND Discharge

Flow

Flow



V.F.W

siphon

Settling Pond

Flow
Structure

Wet lands

Discharge TO
Longo Run

Did not
Sample
NO Flow
at this
time
9/24/09