


Middle Branch Passive Treatment System



Directions to Site:

- From SR120 in Westport, turn onto SR4001 (Kettle Creek Road)
- In approximately 2 miles, turn right onto Twomile Run Road (DCNR Sproul State Forest)
- At first cross intersection, turn left onto Middle Branch Road
- At “Y” bear right and drive past gate (will need key from Sproul State Forest office if gate locked; gate open during hunting season)
- Make first left and then left again at access road gate (will need key from Sproul State Forest office; this gate always locked)
- Continue down access road to treatment system

