

Figure No. 5

Operation Scarlift Sample Point Locations

Data obtained from: Operation Scarlift Report
(SL 185) - March, 1978
Blacklick Creek Watershed
Mine Drainage Pollution Abatement Project

- S Scarlift Sample Point Location
- F AMD Discharge Area
- U Abandoned Structure
- E Dry Strip Mine
- V Erosion-Prone Area
- Z Land Slide Area
- C Open Shaft/Mine Entry
- U Untreated Discharge
- e Vertical Mine Shaft
- Coal Processing Settling Basin
- Dry Strip Mine
- Flooded Strip Mine
- Open Shaft/Mine Entry
- Refuse Pile
- Spoil Pile
- Subsidence Prone Area
- Problem Area
- Active Mine Permits
- Roads
- Streams
- Watershed Boundary

